

License No. 129 Date 9/2/9

33/02 - 286
WATER WELL REPORT

Application No. 61-23803

STATE OF WASHINGTON

Permit No.

(1) OWNER: Name H. L. Morgan & L. C. Logan Address 1025 W. Scenic Hts. Rd. Oak Harbor, WA 98277

(2) LOCATION OF WELL: County Island SW $\frac{1}{4}$ NE $\frac{1}{4}$ Sec. 28 T. 33 N. R. 2E W.M.
Bearing and distance from section or subdivision corner 907' E. & 37' N. of center of Section

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one)
New well ☒ Method: Dug ☐ Bored ☐
Deepened ☐ Cable ☐ Driven ☒
Reconditioned ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 253 ft. Depth of completed well 253 ft.

(8) CONSTRUCTION DETAILS:

Casing installed: _____ " Diam. from _____ ft. to _____ ft.
Threaded ☐ _____ " Diam. from _____ ft. to _____ ft.
Welded ☒ 6 " Diam. from 0 ft. to 247.5 ft.

Perforations: Yes ☐ No ☒

Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐

Manufacturer's Name Johnson
Type Welded Model No. _____
Diam. 5 5/8 Slot size 20 from 247.5 ft. to 253 ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel: _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 20 ft.
Material used in seal Bentonite
Did any strata contain unusable water? Yes ☐ No ☒
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name Goulds
Type: Submersible H.P. 7.5

(8) WATER LEVELS: Land-surface elevation 400 ft.
Static level 230.33 ft. below top of well Date 7/18/73
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☒ No ☐ If yes, by whom? H. Morgan
Yield: 20 gal./min. with 1.33 ft. drawdown after 4 hrs.
" " " " " " " " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level
0:00	231.33				
0:01	230.00				

Date of test 5/15/74

Bailer test _____ gal./min. with _____ ft. drawdown after _____ hrs.

Artesian flow _____ g.p.m. Date _____

Temperature of water _____ Was a chemical analysis made? Yes ☒ No ☐

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Hardpan	0	38
Sand	38	85
Clay	85	118
Sandy	118	122
Gravel	122	230
Water Gravel	230	253
Clay	253	

Work started _____, 19____ Completed July, 1973

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Whidbey Well Drillers
(Person, firm, or corporation) (Type or print)

Address 1143 W. Ft. Nugent Rd. Oak Harbor, WA 98277

[Signed] [Signature] (Well Driller)

License No. 129 Date July, 1973

(USE ADDITIONAL SHEETS IF NECESSARY)